

**2008 Historic Resource Survey
North Side, City of Granbury**

Property No.: 23
1205 Lipan

Preservation Priority:

Low

These properties have no association or unidentified association with history or historic context(s). They have been moderately to severely altered, losing their original character and architectural integrity. These resources usually do not meet National Register criteria or criteria to be designated as Recorded Texas Historic Landmarks.

Construction Date:

Circa 1940s



Resource Type/Subtype:

Building/Commercial

Current Owner(s):

Stylistic Influence:

Brief History:

Area(s) of Significance:

Description of Resource:

Frame construction, vinyl siding
Hipped roof, composition shingles
Fixed and double-hung, aluminum and vinyl windows
Single-door primary entrance
Metal shed roof porch, wood posts, full-width
Rectangular plan

One story

Building added to and changed extensively, maybe in Appraisal District's database as 1125 Lipan Highway

Integrity:

Location, setting

Possible Threats:

Development, major alterations, vacancy

Existing Historical

Designations/Protections:

None