

Site #66

Priority L: (Typifies a common local building form, architectural style, or type, with little or no identified historic associations; is a moderate to severely altered resource that exemplifies a common building type or architectural style, or that has only minor historic significance.)

113 W. Bridge
Granbury
Hood County
Est. 1925

Historic Use: Residence

Present Use: Commercial/Retail

Property Type: N/A

Stylistic Influence: N/A

History of Property: N/A

Areas of Significance (include justification):

Bibliography (include any oral history):

Surveyor: Saltarelli

Date Surveyed: 2001

Photo Data: Roll/Frame M3/0

Description of Building:

Location: Original Location

-Building faces north

-One story frame house

-Center passage plan

-Pier and Beam foundation

-Weatherboard siding

-Wood sash windows (6x6)

-Single door primary entrance

-Gable end treatments same as wall surface with vents

-Gable roof with composition shingles and exposed rafter ends

-Window or door on east side enclosed

