

Site #131

Priority M: (Contributed to local history or broader historical patterns, but alterations have diminished its integrity; is a good but typical example of architecture, engineering, or crafted design; is a good but altered illustration of a common local building form, architectural style or type.)

117 S. Lambert

Granbury

Hood County

Est. 1940

Historic Use: Residential

Present Use: Residential

Property Type: Vernacular House

Stylistic Influence: Minimal Traditional

History of Property: N/A

Areas of Significance (include justification):

Bibliography (include any oral history):

Surveyor: MS

Date Surveyed: 2001

Photo Data: Roll/Frame M6/2

Description of Building:

Location: Original Location

-Building faces west

-One story frame structure

-Center passage plan (two rooms deep)

-Pier and beam foundation

-Weatherboard siding

-One bay, west elevation porch with hipped roof and turned wood posts

-Wood sash, double hung windows (1/1)

-Single door primary entrance

-Hipped roof with composition shingles

-Built on carport

